



## PRODUCT DETAILS

### CALIPER COMPLETE REPAIR KIT



**ARSKAR NEIN** 160 840 402  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

### PRODUKTE ENTHALTEN



#### CALIPER PIN REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 175

**REFERENZNUMMER:** MCK1254, AMMCK1254, ZG070160007, STRMCK1254, 871054



#### CALIPER ACTUATOR SEAL / 1 EINHEIT

**ARSKAR NEIN:** 160 840 269

**REFERENZNUMMER:** -



#### CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT

**ARSKAR NEIN:** 160 840 265

**REFERENZNUMMER:** -



#### CALIPER MANUAL ADJUSTING GEAR / 1 EINHEIT

**ARSKAR NEIN:** 160 840 401

**REFERENZNUMMER:** -



#### CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 634

**REFERENZNUMMER:** -



#### CALIPER NEEDLE BEARING SET / 1 EINHEIT

**ARSKAR NEIN:** 160 840 155

**REFERENZNUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr