



## PRODUCT DETAILS

### CALIPER COMPLETE REPAIR KIT



**ARSKAR NEIN** 160 840 404  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

### PRODUKTE ENHALTEN



**CALIPER PIN REPAIR KIT / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 234  
**REFERENZNUMMER:** MCK1317, 85109889



**CALIPER ACTUATOR SEAL / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 269  
**REFERENZNUMMER:** -



**CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 265  
**REFERENZNUMMER:** -



**CALIPER MANUAL ADJUSTING GEAR / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 266  
**REFERENZNUMMER:** -



**CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 634  
**REFERENZNUMMER:** -



**CALIPER NEEDLE BEARING SET / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 155  
**REFERENZNUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr