



## PRODUCT DETAILS

### CALIPER COMPLETE REPAIR KIT - L



**ARSKAR NEIN** 160 840 340  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

## PRODUKTE ENHALTEN



### CALIPER BOOT & PIN REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 145

**REFERENZNUMMER:** MCK1171, 5021170885, 1489989, AMMCK1171, 98133542AS, CF10438...



### CALIPER SHAFT HOUSING & PISTON SET - L / 1 EINHEIT

**ARSKAR NEIN:** 160 840 306

**REFERENZNUMMER:** DSB6L



### CALIPER MECHANISM REPAIR KIT - L / 1 EINHEIT

**ARSKAR NEIN:** 160 840 301

**REFERENZNUMMER:** DSB5L, CF104620



### CALIPER TAPPET PLATE / 1 EINHEIT

**ARSKAR NEIN:** 160 840 279

**REFERENZNUMMER:** -



### CALIPER CALIBRATION BOLT - L / 2 EINHEIT

**ARSKAR NEIN:** 160 840 418

**REFERENZNUMMER:** -



### CALIPER ECCENTRIC SHAFT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 187

**REFERENZNUMMER:** -



## CONTACT



### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr