



PRODUCT DETAILS

CALIPER COMPLETE REPAIR KIT - L - (WITHOUT LEVER)



ARSKAR NEIN 160 840 632
MARKE MERITOR
PAKET EINHEIT 1 stck

PRODUKTE ENTHALTEN



CALIPER PIN REPAIR KIT / 1 EINHEIT

ARSKAR NEIN: 160 840 195

REFERENZNUMMER: MCK1243, MCK1140, 85107912, 81508026025, 35403112205, 500186...



CALIPER ACTUATOR SEAL / 1 EINHEIT

ARSKAR NEIN: 160 840 227

REFERENZNUMMER: -



CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT

ARSKAR NEIN: 160 840 086

REFERENZNUMMER: -



CALIPER MANUAL ADJUSTING GEAR - L / 1 EINHEIT

ARSKAR NEIN: 160 840 207

REFERENZNUMMER: -



CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT

ARSKAR NEIN: 160 840 634

REFERENZNUMMER: -



CALIPER BEARING SET / 1 EINHEIT

ARSKAR NEIN: 160 840 159

REFERENZNUMMER: SJ4112, 3092329, 1522169



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr