



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



**ARSKAR NEIN**

160 840 153

**MARKE**

MERITOR

**REFERENZNUMMER**

MCK1299, 3092268, 3095628,  
3096769, 85107718, AMMCK1299,  
1522170, STRMCK1299, Y07100312

**PAKET EINHEIT**

1 stck

### PRODUKTE ENTHALTEN



**CALIPER PIN - Ø 35 / 102 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 077

**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M20 X 2 / 125 MM / 2 EINHEIT**

**ARSKAR NEIN:** 160 840 078

**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M20 X 2 / 80 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 081

**REFERENZNUMMER:** -



**CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 EINHEIT**

**ARSKAR NEIN:** 160 840 097

**REFERENZNUMMER:** -



**CALIPER PIN BOOT / 2 EINHEIT**

**ARSKAR NEIN:** 160 840 083

**REFERENZNUMMER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr