



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



**ARSKAR NEIN**

160 840 195

**MARKE**

MERITOR

**REFERENZNUMMER**

MCK1243, MCK1140, 85107912,  
81508026025, 35403112205,  
5001860791, 42552052, 42555201,  
503128758, 0501215220, 1522058

**PAKET EINHEIT**

1 stck

### PRODUKTE ENTHALTEN



**CALIPER PIN - Ø 35 / 144 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 060

**REFERENZNUMMER:** -



**CALIPER PIN - Ø 31 / 84 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 061

**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M18 X 1.5 / 150 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 088

**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M18 X 1.5 / 90 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 089

**REFERENZNUMMER:** -



**CALIPER PIN OVAL BUSH - Ø 31-33 X 42 / 30 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 062

**REFERENZNUMMER:** -



**CALIPER PIN BUSH - Ø 35 X 39 / 30 MM / 2 EINHEIT**

**ARSKAR NEIN:** 160 840 063

**REFERENZNUMMER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr