



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



<b>ARSKAR NON</b>	160 840 195
<b>MARQUE</b>	MERITOR
<b>NUMÉRO DE RÉFÉRENCE</b>	MCK1243, MCK1140, 85107912, 81508026025, 35403112205, 5001860791, 42552052, 42555201, 503128758, 0501215220, 1522058
<b>PAQUET UNITÉ</b>	1 pièces

### PRODUITS INCLUS



**CALIPER PIN - Ø 35 / 144 MM / 1 UNITÉ**

**ARSKAR NON:** 160 840 060  
**NUMÉRO DE RÉFÉRENCE:** -



**CALIPER PIN - Ø 31 / 84 MM / 1 UNITÉ**

**ARSKAR NON:** 160 840 061  
**NUMÉRO DE RÉFÉRENCE:** -



**CALIPER PIN BOLT - M18 X 1.5 / 150 MM / 1 UNITÉ**

**ARSKAR NON:** 160 840 088  
**NUMÉRO DE RÉFÉRENCE:** -



**CALIPER PIN BOLT - M18 X 1.5 / 90 MM / 1 UNITÉ**

**ARSKAR NON:** 160 840 089  
**NUMÉRO DE RÉFÉRENCE:** -



**CALIPER PIN OVAL BUSH - Ø 31-33 X 42 / 30 MM / 1 UNITÉ**

**ARSKAR NON:** 160 840 062  
**NUMÉRO DE RÉFÉRENCE:** -



**CALIPER PIN BUSH - Ø 35 X 39 / 30 MM / 2 UNITÉ**

**ARSKAR NON:** 160 840 063  
**NUMÉRO DE RÉFÉRENCE:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr