



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



<b>ARSKAR NUMMER</b>	160 840 153
<b>MERK</b>	MERITOR
<b>REFERENTIENUMMER</b>	MCK1299, 3092268, 3095628, 3096769, 85107718, AMMCK1299, 1522170, STRMCK1299, Y07100312
<b>PAKKET EENHEID</b>	1 pcs

### PRODUCTEN INBEGREPEN



#### CALIPER PIN - Ø 35 / 102 MM / 1 EENHEID

**ARSKAR NUMMER:** 160 840 077  
**REFERENTIENUMMER:** -



#### CALIPER PIN BOLT - M20 X 2 / 125 MM / 2 EENHEID

**ARSKAR NUMMER:** 160 840 078  
**REFERENTIENUMMER:** -



#### CALIPER PIN BOLT - M20 X 2 / 80 MM / 1 EENHEID

**ARSKAR NUMMER:** 160 840 081  
**REFERENTIENUMMER:** -



#### CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 EENHEID

**ARSKAR NUMMER:** 160 840 097  
**REFERENTIENUMMER:** -



#### CALIPER PIN BOOT / 2 EENHEID

**ARSKAR NUMMER:** 160 840 083  
**REFERENTIENUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr