



PRODUCT DETAILS

CALIPER COMPLETE REPAIR KIT



ARSKAR NEIN 160 840 404
MARKE MERITOR
PAKET EINHEIT 1 stck

PRODUKTE ENHALTEN



CALIPER PIN REPAIR KIT / 1 EINHEIT
ARSKAR NEIN: 160 840 234
REFERENZNUMMER: MCK1317, 85109889



CALIPER ACTUATOR SEAL / 1 EINHEIT
ARSKAR NEIN: 160 840 269
REFERENZNUMMER: -



CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT
ARSKAR NEIN: 160 840 265
REFERENZNUMMER: -



CALIPER MANUAL ADJUSTING GEAR / 1 EINHEIT
ARSKAR NEIN: 160 840 266
REFERENZNUMMER: -



CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT
ARSKAR NEIN: 160 840 634
REFERENZNUMMER: -



CALIPER NEEDLE BEARING SET / 1 EINHEIT
ARSKAR NEIN: 160 840 155
REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr