



## PRODUCT DETAILS

### CALIPER COMPLETE REPAIR KIT - L



**ARSKAR NEIN** 160 840 399  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

### PRODUKTE ENTHALTEN



#### CALIPER PIN REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 133

**REFERENZNUMMER:** MCK1086, 1522185, ZG002950002, 5001858717



#### CALIPER ACTUATOR SEAL / 1 EINHEIT

**ARSKAR NEIN:** 160 840 227

**REFERENZNUMMER:** -



#### CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT

**ARSKAR NEIN:** 160 840 342

**REFERENZNUMMER:** -



#### CALIPER MANUAL ADJUSTING GEAR - L / 1 EINHEIT

**ARSKAR NEIN:** 160 840 207

**REFERENZNUMMER:** -



#### CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 634

**REFERENZNUMMER:** -



#### CALIPER NEEDLE BEARING SET / 1 EINHEIT

**ARSKAR NEIN:** 160 840 155

**REFERENZNUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr