



## PRODUCT DETAILS

### CALIPER COMPLETE REPAIR KIT - L



**ARSKAR NEIN** 160 840 538  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

### PRODUKTE ENTHALTEN



#### CALIPER BOOT & PIN REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 466  
**REFERENZNUMMER:** MCK1170



#### CALIPER SHAFT HOUSING & PISTON SET - L / 1 EINHEIT

**ARSKAR NEIN:** 160 840 517  
**REFERENZNUMMER:** -




#### CALIPER MECHANISM REPAIR KIT - L / 1 EINHEIT

**ARSKAR NEIN:** 160 840 527  
**REFERENZNUMMER:** -



#### CALIPER TAPPET PLATE / 1 EINHEIT

**ARSKAR NEIN:** 160 840 506  
**REFERENZNUMMER:** -



#### CALIPER CALIBRATION BOLT - L / 2 EINHEIT

**ARSKAR NEIN:** 160 840 507  
**REFERENZNUMMER:** -



#### CALIPER ECCENTRIC SHAFT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 460  
**REFERENZNUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr