



PRODUCT DETAILS

CALIPER COMPLETE REPAIR KIT - L



ARSKAR NEIN 160 840 340
MARKE MERITOR
PAKET EINHEIT 1 stck

PRODUKTE ENHALTEN



CALIPER BOOT & PIN REPAIR KIT / 1 EINHEIT

ARSKAR NEIN: 160 840 145

REFERENZNUMMER: MCK1171, 5021170885, 1489989, AMMCK1171, 98133542AS, CF10438...



CALIPER SHAFT HOUSING & PISTON SET - L / 1 EINHEIT

ARSKAR NEIN: 160 840 306

REFERENZNUMMER: DSB6L



CALIPER MECHANISM REPAIR KIT - L / 1 EINHEIT

ARSKAR NEIN: 160 840 301

REFERENZNUMMER: DSB5L, CF104620



CALIPER TAPPET PLATE / 1 EINHEIT

ARSKAR NEIN: 160 840 279

REFERENZNUMMER: -



CALIPER CALIBRATION BOLT - L / 2 EINHEIT

ARSKAR NEIN: 160 840 418

REFERENZNUMMER: -



CALIPER ECCENTRIC SHAFT / 1 EINHEIT

ARSKAR NEIN: 160 840 187

REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr