



PRODUCT DETAILS

CALIPER COMPLETE REPAIR KIT - R



ARSKAR NEIN 160 840 394
MARKE MERITOR
PAKET EINHEIT 1 stck

PRODUKTE ENHALTEN



CALIPER PIN REPAIR KIT / 1 EINHEIT

ARSKAR NEIN: 160 840 133

REFERENZNUMMER: MCK1086, 1522185, ZG002950002, 5001858717



CALIPER ACTUATOR SEAL / 1 EINHEIT

ARSKAR NEIN: 160 840 227

REFERENZNUMMER: -



CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT

ARSKAR NEIN: 160 840 342

REFERENZNUMMER: -



CALIPER MANUAL ADJUSTING GEAR - R / 1 EINHEIT

ARSKAR NEIN: 160 840 017

REFERENZNUMMER: -



CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT

ARSKAR NEIN: 160 840 634

REFERENZNUMMER: -



CALIPER NEEDLE BEARING SET / 1 EINHEIT

ARSKAR NEIN: 160 840 155

REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr