



## PRODUCT DETAILS

### CALIPER COMPLETE REPAIR KIT - R



**ARSKAR NEIN** 160 840 539  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

## PRODUKTE ENHALTEN



#### CALIPER BOOT & PIN REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 466  
**REFERENZNUMMER:** MCK1170



#### CALIPER SHAFT HOUSING & PISTON SET - R / 1 EINHEIT

**ARSKAR NEIN:** 160 840 518  
**REFERENZNUMMER:** -



#### CALIPER MECHANISM REPAIR KIT - R / 1 EINHEIT

**ARSKAR NEIN:** 160 840 528  
**REFERENZNUMMER:** -



#### CALIPER TAPPET PLATE / 1 EINHEIT

**ARSKAR NEIN:** 160 840 506  
**REFERENZNUMMER:** -



#### CALIPER CALIBRATION BOLT - R / 2 EINHEIT

**ARSKAR NEIN:** 160 840 508  
**REFERENZNUMMER:** -



#### CALIPER ECCENTRIC SHAFT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 460  
**REFERENZNUMMER:** -



## CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

[arskar@arskar.com.tr](mailto:arskar@arskar.com.tr)