



## PRODUCT DETAILS

### CALIPER MECHANISM REPAIR KIT - L



<b>ARSKAR NEIN</b>	160 840 301
<b>MARKE</b>	MERITOR
<b>REFERENZNUMMER</b>	DSB5L, CF104620
<b>PAKET EINHEIT</b>	1 stck

### PRODUKTE ENTHALTEN



#### CALIPER ADJUSTING MECHANISM - L / 1 EINHEIT

**ARSKAR NEIN:** 160 840 310  
**REFERENZNUMMER:** -



#### CALIPER ADJUSTER BOLT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 312  
**REFERENZNUMMER:** -



#### CALIPER ADJUSTER SPRING / 1 EINHEIT

**ARSKAR NEIN:** 160 840 313  
**REFERENZNUMMER:** -



#### CALIPER PISTON WAVY WASHER / 2 EINHEIT

**ARSKAR NEIN:** 160 840 314  
**REFERENZNUMMER:** -



#### CALIPER PISTON RING / 2 EINHEIT

**ARSKAR NEIN:** 160 840 315  
**REFERENZNUMMER:** -



#### CALIPER PISTON SEAL / 2 EINHEIT

**ARSKAR NEIN:** 160 840 316  
**REFERENZNUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

[arskar@arskar.com.tr](mailto:arskar@arskar.com.tr)