



## PRODUCT DETAILS

### CALIPER MECHANISM REPAIR KIT - R



<b>ARSKAR NEIN</b>	160 840 304
<b>MARKE</b>	MERITOR
<b>REFERENZNUMMER</b>	MCK1291, 876051, AMMCK1291, 2799438
<b>PAKET EINHEIT</b>	1 stck

### PRODUKTE ENTHALTEN



#### CALIPER ADJUSTING MECHANISM - R / 1 EINHEIT

ARSKAR NEIN: 160 840 311

REFERENZNUMMER: -



#### CALIPER ADJUSTER BOLT / 1 EINHEIT

ARSKAR NEIN: 160 840 312

REFERENZNUMMER: -



#### CALIPER ADJUSTER SPRING / 1 EINHEIT

ARSKAR NEIN: 160 840 313

REFERENZNUMMER: -



#### CALIPER PISTON WAVY WASHER / 2 EINHEIT

ARSKAR NEIN: 160 840 314

REFERENZNUMMER: -



#### CALIPER PISTON RING / 2 EINHEIT

ARSKAR NEIN: 160 840 315

REFERENZNUMMER: -



#### CALIPER PISTON SEAL / 2 EINHEIT

ARSKAR NEIN: 160 840 316

REFERENZNUMMER: -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr