



## PRODUCT DETAILS

### CALIPER PIN BOLT REPAIR KIT



<b>ARSKAR NEIN</b>	160 840 217
<b>MARKE</b>	MERITOR
<b>REFERENZNUMMER</b>	SJ4021, 8550881, 65537710
<b>PAKET EINHEIT</b>	1 stck

### PRODUKTE ENTHALTEN



**CALIPER PIN BOLT - M20 X 1.5 / 150 MM / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 070  
**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M20 X 1.5 / 100 MM / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 294  
**REFERENZNUMMER:** -



**CALIPER PIN CAP - Ø 45 / 14.5 MM / 2 EINHEIT**  
**ARSKAR NEIN:** 160 840 110  
**REFERENZNUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr