



PRODUCT DETAILS

CALIPER PIN REPAIR KIT



ARSKAR NEIN	160 840 396
MARKE	MERITOR
REFERENZNUMMER	MCK1134, SJ4094, 3092255, 3095627, 85103892, AMMCK1134, 1489198
PAKET EINHEIT	1 stck

PRODUKTE ENTHALTEN



CALIPER PIN - Ø 35 / 102 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 077
REFERENZNUMMER: -



CALIPER PIN - Ø 35 / 60 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 080
REFERENZNUMMER: -



CALIPER PIN BOLT - M20 X 2 / 125 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 078
REFERENZNUMMER: -



CALIPER PIN BOLT - M20 X 2 / 80 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 081
REFERENZNUMMER: -



CALIPER PIN FIBER BUSH - Ø 35 X 39 / 38 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 147
REFERENZNUMMER: -



CALIPER PIN OVAL BUSH - Ø 35-36 X 39 / 30 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 176
REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr