



**PRODUCT DETAILS**

**CALIPER TAPPET PLATE REPAIR KIT - L**



**ARSKAR NEIN** 160 840 504  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

**PRODUKTE ENTHALTEN**



**CALIPER TAPPET PLATE / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 506  
**REFERENZNUMMER:** -



**CALIPER CALIBRATION BOLT - L / 2 EINHEIT**  
**ARSKAR NEIN:** 160 840 507  
**REFERENZNUMMER:** -



**CALIPER TAPPET BOLT - M8 X 1.25 / 20 MM / 2 EINHEIT**  
**ARSKAR NEIN:** 160 840 509  
**REFERENZNUMMER:** -



**CONTACT**



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr