



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



<b>ARSKAR NO</b>	160 840 067
<b>BRAND</b>	MERITOR
<b>REFERENCE NUMBER</b>	MCK1102, ST1157, 81508026017, 81508026020, 81508026021, 35503109496, 5001849885, 1522034, 10770779, 0501213164
<b>PACKAGE UNIT</b>	1 pcs

### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşğıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr