



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



<b>ARSKAR NO</b>	160 840 133
<b>BRAND</b>	MERITOR
<b>REFERENCE NUMBER</b>	MCK1086, 1522185, ZG002950002, 5001858717
<b>PACKAGE UNIT</b>	1 pcs

### PRODUCTS INCLUDED



**CALIPER PIN - Ø 35 / 126 MM / 1 UNIT**

**ARSKAR NO:** 160 840 134

**REFERENCE NUMBER:** -



**CALIPER OVAL PIN - Ø 33-35 / 66 MM / 1 UNIT**

**ARSKAR NO:** 160 840 135

**REFERENCE NUMBER:** -



**CALIPER PIN BOLT - M20 X 1.5 / 150 MM / 1 UNIT**

**ARSKAR NO:** 160 840 070

**REFERENCE NUMBER:** -



**CALIPER PIN BOLT - M20 X 1.5 / 90 MM / 1 UNIT**

**ARSKAR NO:** 160 840 071

**REFERENCE NUMBER:** -



**CALIPER PIN BUSH - Ø 35 X 39 / 30 MM / 3 UNIT**

**ARSKAR NO:** 160 840 063

**REFERENCE NUMBER:** -



**CALIPER PIN BOOT RING - Ø 35 X 43 / 2.5 MM / 2 UNIT**

**ARSKAR NO:** 160 840 122

**REFERENCE NUMBER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr