



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



<b>ARSKAR NO</b>	160 840 406
<b>BRAND</b>	MERITOR
<b>REFERENCE NUMBER</b>	MCK1118, 85102092
<b>PACKAGE UNIT</b>	1 pcs

### PRODUCTS INCLUDED



**CALIPER PIN - Ø 35 / 102 MM / 2 UNIT**

**ARSKAR NO:** 160 840 077

**REFERENCE NUMBER:** -



**CALIPER PIN BOLT - M20 X 2 / 125 MM / 2 UNIT**

**ARSKAR NO:** 160 840 078

**REFERENCE NUMBER:** -



**CALIPER PIN FIBER BUSH - Ø 35 X 39 / 77 MM / 1 UNIT**

**ARSKAR NO:** 160 840 253

**REFERENCE NUMBER:** -



**CALIPER PIN OVAL BUSH - Ø 35-36 X 39 / 30 MM / 2 UNIT**

**ARSKAR NO:** 160 840 176

**REFERENCE NUMBER:** -



**CALIPER PIN BOOT RING - Ø 37 X 40 / 11 MM / 2 UNIT**

**ARSKAR NO:** 160 840 105

**REFERENCE NUMBER:** -



**CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 UNIT**

**ARSKAR NO:** 160 840 097

**REFERENCE NUMBER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr