



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



|                         |                  |
|-------------------------|------------------|
| <b>ARSKAR NUMMER</b>    | 160 840 113      |
| <b>MERK</b>             | MERITOR          |
| <b>REFERENTIENUMMER</b> | MCK1065, MCK1066 |
| <b>PAKKET EENHEID</b>   | 1 pcs            |

### PRODUCTEN INBEGREPEN



#### CALIPER PIN - Ø 35 / 102 MM / 1 EENHEID

**ARSKAR NUMMER:** 160 840 077

**REFERENTIENUMMER:** -



#### CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 EENHEID

**ARSKAR NUMMER:** 160 840 097

**REFERENTIENUMMER:** -



#### CALIPER PIN BOOT / 2 EENHEID

**ARSKAR NUMMER:** 160 840 083

**REFERENTIENUMMER:** -



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr