



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



**ARSKAR NUMMER**

160 840 405

**MERK**

MERITOR

**REFERENTIENUMMER**

MCK1135, SJ4107, 3092256,  
3096768, 85103891, 1522166

**PAKKET EENHEID**

1 pcs

### PRODUCTEN INBEGREPEN



**CALIPER PIN - Ø 35 / 102 MM / 2 EENHEID**

**ARSKAR NUMMER:** 160 840 077

**REFERENTIENUMMER:** -



**CALIPER PIN BOLT - M20 X 2 / 125 MM / 2 EENHEID**

**ARSKAR NUMMER:** 160 840 078

**REFERENTIENUMMER:** -



**CALIPER PIN FIBER BUSH - Ø 35 X 39 / 38 MM / 2 EENHEID**

**ARSKAR NUMMER:** 160 840 147

**REFERENTIENUMMER:** -



**CALIPER PIN OVAL BUSH - Ø 35-36 X 39 / 30 MM / 2 EENHEID**

**ARSKAR NUMMER:** 160 840 176

**REFERENTIENUMMER:** -



**CALIPER PIN BOOT RING - Ø 37 X 40 / 11 MM / 2 EENHEID**

**ARSKAR NUMMER:** 160 840 105

**REFERENTIENUMMER:** -



**CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 EENHEID**

**ARSKAR NUMMER:** 160 840 097

**REFERENTIENUMMER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr