



## PRODUCT DETAILS

### HAUPTBREMSZYLINDER



|                       |   |
|-----------------------|---|
| <b>ARSKAR NEIN</b>    | 25.0026.00  |
| <b>MARKE</b>          | MERCEDES  |
| <b>REFERENZNUMMER</b> | H31708.0.5, S26, 0004302401,<br>0004305501, 0014305501, 184264,<br>02458263, 02458451, 03414766,<br>0600374, K28228, 51572810271,<br>1355460017, 13554617,<br>1525431256020, 1586360335,<br>158636335 |
| <b>EINZELHEITEN</b>   | Bohrung-Ø [mm] : 31.75  |
| <b>PAKET EINHEIT</b>  | 1 stck  |
| <b>GEWICHT</b>        | 3.36  |

### PRODUKTE ENHALTEN



#### REPARATURSATZ, HAUPTBREMSZYLINDER / 1 EINHEIT

**ARSKAR NEIN:** RK.0026

**REFERENZNUMMER:** RK31540, 81511306016, 02966163, 08124577, 2966163,  
875128900...



### CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr